



ROSSI®

SAFETY WARNING

Rossi is issuing a voluntary safety warning on .38 Special and .357 Magnum revolvers made between the years 2005 and 2017 that may have a condition that could cause, under certain circumstances, the revolver to fire if dropped

This Safety Warning covers .38 Special and .357 Magnum revolver models R351, R352, 461, R462, R851, R971, and R972 with serial numbers beginning with the letter Y, Z, or A through K.

Rossi is developing inspection and repair solutions. Rossi will make every effort possible to ensure Rossi Revolvers will be inspected, serviced if necessary, and returned to customers in a prompt, timely fashion.

Issues underlying this Safety Warning are currently pending before the court in a proposed class action lawsuit pending in the United States District Court for the Southern District of Florida styled Burrow v. Forjas Taurus, S.A., civil action file no. 1:16-cv-21606-EGT

ACTIONS TO BE TAKEN:

Stop using your revolver immediately.

SEARCH YOUR SERIAL NUMBER

SEARCH

IF YOUR SERIAL NUMBER IS FOUND, STOP USING YOUR REVOLVER IMMEDIATELY AND FOLLOW OUR INSTRUCTIONS SO WE CAN INSPECT AND, IF NECESSARY, REPAIR YOUR REVOLVER.